


advantage. While I have the older style board which has the exact shape of its rudder, the newer diamond boards are housed in similar trunks, I believe they could be repaired in the same manner.

Cross Section of entire
Centerboard Mechanism



RED pennant line (approx. 2 feet) is hanging under boat

while CB is stuck in Keel.